Risk Assessment - White Line Painting of Platform Edges

Reference No: CON-44490-38
Version No: 2
Assessment Approver: Kevin Jarvis

Department: Construction and Maintenance
Date Of Assessment: 21 October 2021
Review Due Before: 07 December 2029
Lead Assessor: Chris Helm
Team: Jim Hitchen & Kevin Jarvis

Painting while lines on platform edges

Type	Hazard Cause	Persons Affected	Control Measures	L S T Overall	Additional Control Measures	L S T Overall	Owner/Action
Health and Safety	Slips, trips, falls, being struck by a train or other injury whilst painting Platforms have open edges and trains can through them.	Volunteers & Staff	1) CRITICAL - Engineering: Do not stand on the rail to gain height. - Effective 2) Engineering: Short ladders should be used from track level if extra height is needed - Effective 3) CRITICAL - Administrative: Work can only take place on non-running days after consultation and approval from the Operations Manager - Effective 4) CRITICAL - Administrative: When working at platform level, workers should keep a safe distance between them and the platform edge - Effective 5) Administrative: Keep other staff and pasengers away from the work areas with barriers or hazard tape as necessary - Effective 6) CRITICAL - Administrative: Sweep platforms clean of debris and dust before starting work to reduce risk of particles entering the eyes - Effective 7) CRITICAL - Administrative: Those involved in the activity should be Personal track Safety (PTS) trained. - Effective 8) CRITICAL - PPE: Hi-viz jacket, overalls, gloves, safety glasses and safety footwear should be worn - Effective	1 x 2 = 2 Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.	None	1 x 2 = 2 Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.	n/a

COSHH Assessments

There are no COSHH assessments associated with this risk assessment.
Ends

Appendix



Reference: UI-44490-636
Platform White Line -