Gloucestershire Warwickshire Steam Railway Plc

# WD-40 Fast drying Contact Cleaner

## COSHH Assessment Details

| | | | |
|---|---|---|---|
| **Assessment Id:** | COSHH-45294-63 | **Lead Assessor:** | Kevin Jarvis |
| **Version No:** | 2 | **Published Date:** | 25 February 2025 |
| **Status:** | Active | **Review Date:** | 25 February 2028 |
| **Assessment Date:** | 25 February 2025 | **Approved By:** | Kevin Jarvis |

## Substance Details

| | | | |
|---|---|---|---|
| **Substance Name:** | WD-40 Fast drying Contact Cleaner | **Substance Use:** | Spray Can contact cleaner |
| **Manufacturer** | WD40 Ltd | **Emergency Tel No:** | 0238073798 |
| **Address:** | PO Box 440<br>Kiln Farm<br>Milton Keynes<br>MK1 3LF | | |
| **Form Of Substance:** | Liquid, Mist, Vapour, | **Routes of Exposure** | Inhalation, Skin, Ingestion, Eyes, |
| **Storage and Handling** | Store in manufacturers container in a COSHH cupboard | | |

**Exposure Limits**

**WEL:** Unknown **LEL:** Unknown **SEL:** Unknown

## Substance Classifications



Harmful



Flammable



Dangerous to the enviroment

### Health Phrases

H304 - May be fatal if swallowed and enters airways.
H315 - Causes skin irritation.
H319 - Causes serious eye irritation.
H336 - May cause drowsiness or dizziness.
H222 - Extremely flammable aerosol.
H229 - Pressurised container. May burst if heated.
H411 - Toxic to aquatic life with long lasting effects.

### Precautionary Phrases

P101 - If medical advice is needed, have product container or label at hand.
P102 - Keep out of reach of children.
P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
P211 - Do not spray on an open flame or other ignition source.

P251 - Do not pierce or burn, even after use.
P261 - Avoid breathing dust/fume/gas/mist/vapours/spray.
P273 - Avoid release to the environment.
P305 + P351 + P3 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P312 - Call a POISON CENTER/doctor/999 if you feel unwell.
P410 + P412 - Protect from sunlight. Do no expose to temperatures exceeding 50°C/ 122°F.
P501 - Dispose of contents/container via an approved disposal route

## Required Personal Protection Equipment (PPE)


Gloves


Goggles

## Control Measures

Current:
• Administrative - Follow manufacturers advice. - Effective
Potential:
No Potential Control Measures
Score Notes:

## Assessment Score

Liklihood of Harm:
1) Very low probability – unlikely/once every 20 years

Severity of Harm:
2) Injury – up to 7 days lost time days lost time

Overall:
Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

## Reference Documents

WD 40 Fast drying Contact Cleaner SDS - Safety Data Sheet

## Appendix

# WD-40 Fast drying Contact Cleaner




**Reference: UI-45294-389**
WD40 Fast drying Contact Cleaner
Picture -