



Gloucestershire Warwickshire Steam Railway Plc
Risk Assessment for Use of locos with non-operational Drivers Safety Device (DSD) - Diesel Loco

**Risk Assessment - Use of locos with non-operational
Drivers Safety Device (DSD)**

Reference No: DIE-44522-28

Version No: 2

Assessment Approver: Kevin Jarvis

Department: Diesel Loco
Date Of Assessment: 22 November 2021
Review Due Before: 05 December 2029
Lead Assessor: Andy Durham
Team: Paul Good & Kevin Jarvis

Use of locos with non operational DSD.

Type	Hazard Cause	Persons Affected	Control Measures	L Overall	S	T	Additional Control Measures	L Overall	S	T	Owner/Action
Health and Safety	Loco/DMU continues to move when the driver incapacitated. Faulty equipment	Everyone	1) CRITICAL - Engineering: If DSD is fitted and operational it should be tested at the start of every day of usage. - Effective 2) CRITICAL - Engineering: Functionality of DSD to be confirmed during 'A' and 'B' examinations. - Effective 3) CRITICAL - Engineering: If defects are present in the DSD system and spare parts or repairs are viable then the DSD must be repaired and reinstated as soon as possible. - Effective 4) CRITICAL - Administrative: All train crew to be subject to and successfully pass the GWSR medical examination. - Effective 5) CRITICAL - Administrative: Only locos with inoperative DSD two train crew must be present in the cab at all times. - Effective 6) CRITICAL - Administrative: Locos with inoperative DSD must have signage in the cab to indicate as such. - Effective 7) CRITICAL - Administrative: GWR operates at a low maximum speed of 25mph. - Effective	1 x 4 = 4	None Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.			n	n	n	n/a

COSHH Assessments

There are no COSHH assessments associated with this risk assessment.

Ends