

Gloucestershire Warwickshire Steam Railway Plc Risk Assessment for Youth Group washing locomotives - OnTrack

Version No: 1

Assessment Approver: Kevin Jarvis

Risk Assessment - Youth Group washing locomotives
Reference No: ONT-45820-2

The Youth group will occasionally have the opportunity to assist the loco departments in cleaning both steam and diesel locomotives.

Department: OnTrack

Date Of Assessment: 12 June 2025 Review Due Before: 07 July 2030 Lead Assessor: Richard Scott

Team: Kev Jarvis

Washing locos

Туре	Hazard Cause	Persons Affected	Control Measures	L S T Overall	Additional Control Measures	L S T Owner/Action Overall
Health and Safety	Personal Injury Slips, trips, falls, impact etc caused by lack of supervision, understanding or knowledge	Volunteers & Staff	1) CRITICAL - Elimination: Cleaning activity to be carried out from ground level or from a mobile platform Effective 2) CRITICAL - Engineering: Locos to be sited outside and on flat concrete ground Effective 3) CRITICAL - Engineering: Risk of falls in pits to be minimised by the use of barriers, tape and positioning of the locos Effective 4) CRITICAL - Administrative: A DBS leader to be present at all times in the work area Effective 5) CRITICAL - Administrative: Youths must not climb or walk on running boards or any other part of a loco Effective 6) CRITICAL - Administrative: Youths must not overstretch on platforms or lean outwards Effective 7) CRITICAL - Administrative: COSHH data to be available for all cleaning products and manufacturers advise followed Effective 8) CRITICAL - Administrative: No horseplay with hoses or water allowed under any circumstances Effective 9) CRITICAL - Administrative: Beware of hot surfaces Effective 10) CRITICAL - Administrative: Beware of electrical hazards Effective 11) CRITICAL - Administrative: Do not allow water into electrical equipment or components Effective 13) CRITICAL - Administrative: Shunting activity or other loco movements are not allowed in or around the work activity area Effective 14) CRITICAL - Administrative: Youths must not enter pit areas Effective 15) CRITICAL - Administrative: Do not allow water to enter locomotives via grills, windows, chimneys, exhaust ports, doors or other openings Effective 16) CRITICAL - PPE: Hi Viz, overalls, safety footwear and gloves to be worn at all times Effective	Low - Risk to be monitored ensure it remains adequately controlled to a acceptable level.		1 x 2 = 2 n/a Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

COSHH Assessments

There are no COSHH assessments associated with this risk assessment. Ends