



Gloucestershire Warwickshire Steam Railway Plc

Flexacryl Cementone Roof Repairer

COSHH Assessment Details

Assessment Id:	COSHH-44270-60	Lead Assessor:	Kevin Jarvis
Version No:	2	Published Date:	11 April 2024
Status:	Active	Review Date:	11 April 2027
Assessment Date:	11 April 2024	Approved By:	Kevin 'Kev' Jarvis

Substance Details

Substance Name:	Flexacryl Cementone Roof Repairer	Substance Use:	Roof repairs to carriages
Manufacturer	Bostik Limited	Emergency Tel No:	01785 272650
Address:	COMMON ROAD STAFFORD STAFFORDSHIRE ST16 3EH		
Form Of Substance:	Liquid, Vapour,	Routes of Exposure	Inhalation, Ingestion, Skin, Eyes,
Storage and Handling	Store in manufacturers container in a COSHH cupboard.		
Exposure Limits			
WEL: 375 mg/m3	LEL: Unknown	SEL: 560 mg/m3	

Substance Classifications



Flammable

Health Phrases

H226 - Flammable liquid and vapour.

Precautionary Phrases

P102 - Keep out of reach of children.

P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.

P233 - Keep container tightly closed.

P280 - Wear protective gloves/protective clothing/eye protection/face protection.

P501 - Dispose of contents/container via an approved disposal route

P240 - Ground and bond container and receiving equipment.

P241 - Use explosion-proof equipment.

P242 - Use non-sparking tools.

P243 - Take action to prevent static discharges.

P302 + P352 - IF ON SKIN: Wash with plenty of water.



Gloucestershire Warwickshire Steam Railway Plc

Flexacryl Cementone Roof Repairer

P403 + P235 - Store in a well-ventilated place. Keep cool.
P370 + P378 - In case of fire: Use... to extinguish.

Required Personal Protection Equipment (PPE)



Respirator



Goggles

Control Measures

Current:

- Administrative - Follow manufacturers advice - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Liklihood of Harm:

2) Low probability – seldom/once every 5 years

Severity of Harm:

2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

Reference Documents

Flexacryl Roof Repairer Safety Data Sheet - Flexacryl Roof Repairer MSDS

Appendix



Reference: UI-44270-292

Flexacryl Roof Repairer - Flexacryl
Roof Repairer Picture