



Gloucestershire Warwickshire Steam Railway Plc SPEC 81 UNDERFRAME

- P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P312 - Call a POISON CENTER/doctor/999 if you feel unwell.
P331 - Do NOT induce vomiting.
P340 - Remove person to fresh air and keep comfortable for breathing.
P352 - Wash with plenty of water.
P361 - Take off immediately all contaminated clothing.
P401 - Store in accordance with MSDS
P501 - Dispose of contents/container via an approved disposal route

Required Personal Protection Equipment (PPE)



Gloves



Overalls



Goggles

Control Measures

Current:

- Administrative - Follow manufacturers control measures - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Likelihood of Harm:

2) Low probability – seldom/once every 5 years

Severity of Harm:

2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

Reference Documents

SPEC 81 UNDERFRAME PAINT - SPEC 81 UNDERFRAME PAINT data sheet