



Gloucestershire Warwickshire Steam Railway Plc TN1 - TANNIN BUFFER

Required Personal Protection Equipment (PPE)



Gloves



Overalls



Goggles

Control Measures

Current:

- Administrative - Follow manufacturers advice - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Likelihood of Harm:

2) Low probability – seldom/once every 5 years

Severity of Harm:

2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

Reference Documents

TN1 Tanning Buffer Data Sheet - TN1 Tanning Buffer MSDS

Appendix



Gloucestershire Warwickshire Steam Railway Plc TN1 - TANNIN BUFFER



Reference: UI-44202-678

TN1 Tanning Buffer - TN1 Tanning
Buffer picture