



Gloucestershire Warwickshire Steam Railway Plc

TN1 - TANNIN BUFFER

COSHH Assessment Details

Assessment Id:	COSHH-44202-87	Lead Assessor:	Kevin Jarvis
Version No:	3	Published Date:	03 September 2024
Status:	Active	Review Date:	03 September 2027
Assessment Date:	03 September 2024	Approved By:	Kevin Jarvis

Substance Details

Substance Name:	TN1 - TANNIN BUFFER	Substance Use:	Water treatment chemical for locomotives.
Manufacturer	DTK Water	Emergency Tel No:	01604 686995
Address:	4 Morris Close Park Farm Industrial Estate Wellingborough Northamptonshire NN8 6XF		

Form Of Substance:	Solid,	Routes of Exposure	Inhalation, Skin, Ingestion, Eyes,
---------------------------	--------	---------------------------	---------------------------------------

Storage and Handling Store in manufacturers container in a COSHH cupboard.

Exposure Limits

WEL: Unknown	LEL: Unknown	SEL: Unknown
---------------------	---------------------	---------------------

Substance Classifications



Harmful

Health Phrases

H302 - Harmful if swallowed.
H319 - Causes serious eye irritation.
H412 - Harmful to aquatic life with long lasting effects.
H315 - Causes skin irritation.

Precautionary Phrases

P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P321 - Specific treatment. Refer to MSDS
P301 + P312 - IF SWALLOWED: Call a POISON CENTER/doctor/999 if you feel unwell.
P302 + P352 - IF ON SKIN: Wash with plenty of water.
P305 + P351 + P3 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P362 - Take off contaminated clothing.



Gloucestershire Warwickshire Steam Railway Plc TN1 - TANNIN BUFFER

Required Personal Protection Equipment (PPE)



Gloves



Overalls



Goggles

Control Measures

Current:

- Administrative - Follow manufacturers advice - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Likelihood of Harm:

2) Low probability – seldom/once every 5 years

Severity of Harm:

2) Injury – up to 7 days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

Reference Documents

TN1 Tanning Buffer Data Sheet - TN1 Tanning Buffer MSDS

Appendix



Gloucestershire Warwickshire Steam Railway Plc TN1 - TANNIN BUFFER



Reference: UI-44202-678

TN1 Tanning Buffer - TN1 Tanning
Buffer picture