

Gloucestershire Warwickshire Steam Railway Plc Risk Assessment for White Line Painting of Platform Edges - Construction and Maintenance

Risk Assessment - White Line Painting of Platform EdgesReference No: CON-44490-38 Version No: 2

Assessment Approver: Kevin Jarvis

Department: Construction and Maintenance Date Of Assessment: 21 October 2021 Review Due Before: 07 December 2029

Lead Assessor: Chris Helm Team: Jim Hitchen & Kevin Jarvis

Painting while lines on platform edges

Туре	Hazard Cause	Persons Affected	Control Measures	L S T Overall	Additional Control Measures	L S T Owner/Action Overall
Health and Safety	Slips, trips, falls, being struck by a train or other injury whilst painting Platforms have open edges and trains can through them.	Volunteers & Staff	1) CRITICAL - Engineering: Do not stand on the rail to gain height Effective 2) Engineering: Short ladders should be used from track level if extra height is needed - Effective 3) CRITICAL - Administrative: Work can only take place on non-running days after consultation and approval from the Operations Manager - Effective 4) CRITICAL - Administrative: When working at platform level, workers should keep a safe distance between them and the platform edge - Effective 5) Administrative: Keep other staff and pasengers away from the work areas with barriers or hazard tape as necessary - Effective 6) CRITICAL - Administrative: Sweep platforms clean of debris and dust before starting work to reduce risk of particles entering the eyes - Effective 7) CRITICAL - Administrative: Those involved in the activity should be Personal track Safety (PTS) trained Effective 8) CRITICAL - PPE: Hi-viz jacket, overalls, gloves, safety glasses and safety footwear should be worn - Effective	1 x 2 = 2 Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.	None	1 x 2 = 2 n/a Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

COSHH Assessments

There are no COSHH assessments associated with this risk assessment. Ends

Gloucestershire Warwickshire Steam Railway Plc Risk Assessment for White Line Painting of Platform Edges - Construction and Maintenance

Appendix



Reference: UI-44490-636 Platform White Line -