



Gloucestershire Warwickshire Steam Railway Plc
Risk Assessment for RATS - Museum Coach at Toddington - Toddington Station

Risk Assessment - RATS - Museum Coach at Toddington

Reference No: TOD-44601-0
 Version No: 1
 Assessment Approver: Philip Moore

RATS use an old GWR carriage as a museum located in the bay platform.

Department: Toddington Station
 Date Of Assessment: 09 February 2022
 Review Due Before: 15 March 2029
 Lead Assessor: John Forkes
 Team: Mike Dodd

Use of RATS museum carriage

Type	Hazard Cause	Persons Affected	Control Measures	L Overall	S T	Additional Control Measures	L Overall	S T	Owner/Action	
Health and Safety	Person falling between carriage and platform Trip, slip, fall down gap between platform and carriage	Everyone	1) CRITICAL - Engineering: Platform at correct gauge ad height. - Effective 2) CRITICAL - Engineering: Install a short metal bridge plate (chequer plate) between platform edge and carriage entrance. - Effective 3) CRITICAL - Engineering: Barrier at either end - Effective	2 x 2 = 4 Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.	4	None	n	n	n	n/a
Health and Safety	Damage to carriage or other infrastructure if the carriage is moved Bridge plate not removed before moving	Volunteers & Staff		No Potential Score Available		None	n	n	n	n/a

COSHH Assessments

There are no COSHH assessments associated with this risk assessment.
 Ends