



# Gloucestershire Warwickshire Steam Railway Plc Arrow Dri-Lube

## COSHH Assessment Details

<b>Assessment Id:</b>	COSHH-45294-87	<b>Lead Assessor:</b>	Kevin Jarvis
<b>Version No:</b>	1	<b>Published Date:</b>	03 January 2024
<b>Status:</b>	Active	<b>Review Date:</b>	03 January 2027
<b>Assessment Date:</b>	03 January 2024	<b>Approved By:</b>	Kevin 'Kev' Jarvis

## Substance Details

<b>Substance Name:</b>	Arrow Dri-Lube	<b>Substance Use:</b>	Spray on lubricant
<b>Manufacturer</b>	Arrow Solutions	<b>Emergency Tel No:</b>	01865 407333
<b>Address:</b>	Rawdon Road, Moira, Swadlincote, Derbyshire. DE12 6DA		

**Form Of Substance:** Liquid, Mist, Vapour,      **Routes of Exposure** Inhalation, Skin, Ingestion, Eyes,

**Storage and Handling** Store in manufacturers container in a COSHH cupboard

### Exposure Limits

**WEL:** 2085 mg/m3

**LEL:** Unknown

**SEL:** Unknown

## Substance Classifications



Harmful



Flammable



Dangerous to  
the  
environment

### Health Phrases

H222 - Extremely flammable aerosol.  
H315 - Causes skin irritation.  
H336 - May cause drowsiness or dizziness.  
H411 - Toxic to aquatic life with long lasting effects.

### Precautionary Phrases

P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.  
P211 - Do not spray on an open flame or other ignition source.  
P251 - Do not pierce or burn, even after use.  
P261 - Avoid breathing dust/fume/gas/mist/vapours/spray.  
P271 - Use only outdoors or in a well-ventilated area.  
P273 - Avoid release to the environment.  
P302 + P352 - IF ON SKIN: Wash with plenty of water.

COSHH - Arrow Dri-Lube - Generated 24/05/2026 at 14:57:59



## Gloucestershire Warwickshire Steam Railway Plc Arrow Dri-Lube

P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.  
P312 - Call a POISON CENTER/doctor/999 if you feel unwell.  
P332 + P313 - If skin irritation occurs: Get medical advice/attention.  
P410 + P412 - Protect from sunlight. Do not expose to temperatures exceeding 50°C/ 122°F.  
P501 - Dispose of contents/container via an approved disposal route  
P280 - Wear protective gloves/protective clothing/eye protection/face protection.

### Required Personal Protection Equipment (PPE)



Gloves



Goggles

### Control Measures

#### Current:

• Administrative - Follow manufacturers advice. - Effective

#### Potential:

No Potential Control Measures

Score Notes:

### Assessment Score

Likelihood of Harm:

1) Very low probability – unlikely/once every 20 years

Severity of Harm:

2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

### Reference Documents

Arrow Dri-Lube SDS - Safety Data Sheet

### Appendix



## Gloucestershire Warwickshire Steam Railway Plc Arrow Dri-Lube

---



Reference: UI-45294-572  
Arrow Dri-Lube picture -