



Gloucestershire Warwickshire Steam Railway Plc SPEC 81 ANTI CORROSIVE PRIMER

P102 - Keep out of reach of children.
P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
P312 - Call a POISON CENTER/doctor/999 if you feel unwell.
P331 - Do NOT induce vomiting.
P342 + P311 - If experiencing respiratory symptoms: Call a POISON CENTER/doctor/999
P302 + P352 - IF ON SKIN: Wash with plenty of water.
P351 - Rinse cautiously with water for several minutes.
P361 - Take off immediately all contaminated clothing.
P401 - Store in accordance with MSDS
P501 - Dispose of contents/container via an approved disposal route

Required Personal Protection Equipment (PPE)



Gloves



Goggles

Control Measures

Current:

• Administrative - Follow all manufacturers control measures - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Likelihood of Harm:
Not Set

Severity of Harm:
Not Set

Overall:
No Rating Available

Reference Documents

SPEC 81 ANTI CORROSIVE PRIMER - SPEC 81 ANTI CORROSIVE PRIMER data sheet