



# Gloucestershire Warwickshire Steam Railway Plc

## FryStandard Fryolux Paint

### COSHH Assessment Details

<b>Assessment Id:</b>	COSHH-44081-95	<b>Lead Assessor:</b>	Kevin Jarvis
<b>Version No:</b>	3	<b>Published Date:</b>	03 September 2024
<b>Status:</b>	Active	<b>Review Date:</b>	03 September 2027
<b>Assessment Date:</b>	03 September 2024	<b>Approved By:</b>	Kevin Jarvis

### Substance Details

<b>Substance Name:</b>	FryStandard Fryolux Paint	<b>Substance Use:</b>	General purpose industrial solder
<b>Manufacturer</b>	The Solder Connection	<b>Emergency Tel No:</b>	01291 624400
<b>Address:</b>	Unit 5 Severn Link Distribution Centre, Chepstow, Monmouthshire, NP16 6UN		
<b>Form Of Substance:</b>	Liquid, Vapour,	<b>Routes of Exposure</b>	Inhalation, Skin, Ingestion, Eyes,
<b>Storage and Handling</b>	Store in manufacturers container in a COSHH cupboard.		
<b>Exposure Limits</b>			
<b>WEL:</b> 0.1 mg/m <sup>3</sup>	<b>LEL:</b> Unknown	<b>SEL:</b> 0.2 mg/m <sup>3</sup>	

### Substance Classifications



Toxic



Corrosive



Dangerous to the environment

### Health Phrases

H302 - Harmful if swallowed.  
H314 - Causes severe skin burns and eye damage.  
H332 - Harmful if inhaled.  
H335 - May cause respiratory irritation.  
H411 - Toxic to aquatic life with long lasting effects.

### Precautionary Phrases

P260 - Do not breathe dust/fume/gas/mist/vapours/spray.  
P261 - Avoid breathing dust/fume/gas/mist/vapours/spray.  
P264 - Wash thoroughly after handling.  
P270 - Do not eat, drink or smoke when using this product.  
P271 - Use only outdoors or in a well-ventilated area.  
P273 - Avoid release to the environment.  
P280 - Wear protective gloves/protective clothing/eye protection/face protection.  
P301 + P312 - IF SWALLOWED: Call a POISON CENTER/doctor/999 if you feel unwell.



## Gloucestershire Warwickshire Steam Railway Plc FryStandard Fryolux Paint

P301 + P330 + P3 - IF SWALLOWED: rinse mouth. Do NOT induce vomiting.  
P303 + P361 + P3 - IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].  
P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.  
P305 + P351 + P3 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.  
P312 - Call a POISON CENTER/doctor/999 if you feel unwell.  
P321 - Specific treatment. Refer to MSDS  
P330 - Rinse mouth.  
P363 - Wash contaminated clothing before reuse.  
P391 - Collect spillage.  
P403 + P233 - Store in a well-ventilated place. Keep container tightly closed.  
P405 - Store locked up.  
P501 - Dispose of contents/container via an approved disposal route

### **Required Personal Protection Equipment (PPE)**



Gloves



Overalls



Goggles

### **Control Measures**

#### Current:

- Administrative - Follow manufacturers control measures - Effective

#### Potential:

- Engineering - Consider fume extraction - Effective

Score Notes:

### **Assessment Score**

Liklihood of Harm:

2) Low probability – seldom/once every 5 years

Severity of Harm:

2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

### **Appendix**



## Gloucestershire Warwickshire Steam Railway Plc FryStandard Fryolux Paint

---



**Reference: UI-44081-663**  
Fryolux Solder Paint picture -  
Fryolux Solder Paint picture