



# Gloucestershire Warwickshire Steam Railway Plc WD-40 Fast drying Contact Cleaner

## COSHH Assessment Details

<b>Assessment Id:</b>	COSHH-45294-63	<b>Lead Assessor:</b>	Kevin Jarvis
<b>Version No:</b>	2	<b>Published Date:</b>	25 February 2025
<b>Status:</b>	Active	<b>Review Date:</b>	25 February 2028
<b>Assessment Date:</b>	25 February 2025	<b>Approved By:</b>	Kevin Jarvis

## Substance Details

<b>Substance Name:</b>	WD-40 Fast drying Contact Cleaner	<b>Substance Use:</b>	Spray Can contact cleaner
<b>Manufacturer</b>	WD40 Ltd	<b>Emergency Tel No:</b>	0238073798
<b>Address:</b>	PO Box 440 Kiln Farm Milton Keynes MK1 3LF		
<b>Form Of Substance:</b>	Liquid, Mist, Vapour,	<b>Routes of Exposure</b>	Inhalation, Skin, Ingestion, Eyes,
<b>Storage and Handling</b>	Store in manufacturers container in a COSHH cupboard		

### Exposure Limits

**WEL:** Unknown                      **LEL:** Unknown                      **SEL:** Unknown

## Substance Classifications



Harmful



Flammable



Dangerous to  
the  
enviroment

### Health Phrases

H304 - May be fatal if swallowed and enters airways.  
H315 - Causes skin irritation.  
H319 - Causes serious eye irritation.  
H336 - May cause drowsiness or dizziness.  
H222 - Extremely flammable aerosol.  
H229 - Pressurised container. May burst if heated.  
H411 - Toxic to aquatic life with long lasting effects.

### Precautionary Phrases

P101 - If medical advice is needed, have product container or label at hand.  
P102 - Keep out of reach of children.  
P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.  
P211 - Do not spray on an open flame or other ignition source.



## Gloucestershire Warwickshire Steam Railway Plc WD-40 Fast drying Contact Cleaner

P251 - Do not pierce or burn, even after use.

P261 - Avoid breathing dust/fume/gas/mist/vapours/spray.

P273 - Avoid release to the environment.

P305 + P351 + P3 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

P312 - Call a POISON CENTER/doctor/999 if you feel unwell.

P410 + P412 - Protect from sunlight. Do not expose to temperatures exceeding 50°C/ 122°F.

P501 - Dispose of contents/container via an approved disposal route

### Required Personal Protection Equipment (PPE)



Gloves



Goggles

### Control Measures

#### Current:

- Administrative - Follow manufacturers advice. - Effective

#### Potential:

No Potential Control Measures

Score Notes:

### Assessment Score

Likelihood of Harm:

- 1) Very low probability – unlikely/once every 20 years

Severity of Harm:

- 2) Injury – up to 7 days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

### Reference Documents

WD 40 Fast drying Contact Cleaner SDS - Safety Data Sheet

### Appendix



## Gloucestershire Warwickshire Steam Railway Plc WD-40 Fast drying Contact Cleaner

---



**Reference: UI-45294-389**

WD40 Fast drying Contact Cleaner  
Picture -