



Gloucestershire Warwickshire Steam Railway Plc TFR Gold XQ1CCHC3pwss Cleaner

COSHH Assessment Details

Assessment Id:	COSHH-44859-93	Lead Assessor:	kevin.jarvis
Version No:	2	Published Date:	14 January 2026
Status:	Active	Review Date:	14 January 2029
Assessment Date:	14 January 2026	Approved By:	Kevin Jarvis

Substance Details

Substance Name:	TFR Gold XQ1CCHC3pwss Cleaner	Substance Use:	Pressure washer cleaner used primarily in the loco depts
Manufacturer	Pressure Washer Sales & Service	Emergency Tel No:	01386 860032
Address:	Unit 32 Craycombe Farm, Fladbury, Pershore, Worcs. WR10 2QS		
Form Of Substance:	Liquid, Vapour,	Routes of Exposure	Skin, Eyes, Inhalation, Ingestion,
Storage and Handling	Must be stored in suitable sealed containers in a dry cool location		
Exposure Limits			
WEL: 2 mg/m3	LEL: Unknown	SEL: Unknown	

Substance Classifications



Corrosive



Serious long term health hazard

Health Phrases

H315 - Causes skin irritation.
H318 - Causes serious eye damage.
H351 - Suspected of causing cancer

Precautionary Phrases

P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P302 + P352 - IF ON SKIN: Wash with plenty of water.
P305 + P351 + P3 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



Gloucestershire Warwickshire Steam Railway Plc TFR Gold XQ1CCHC3pwss Cleaner

P308 + P313 - IF exposed or concerned: Get medical advice/attention.
P332 + P313 - If skin irritation occurs: Get medical advice/attention.
P337 + P313 - If eye irritation persists: Get medical advice/attention.
P362 - Take off contaminated clothing.
P405 - Store locked up.

Required Personal Protection Equipment (PPE)



Gloves



Goggles

Control Measures

Current:

- Administrative - Follow manufacturers advice - Effective

Potential:

No Potential Control Measures

Score Notes:

Assessment Score

Likelihood of Harm:

- 1) Very low probability – unlikely/once every 20 years

Severity of Harm:

- 2) Injury – up to 7 days lost time days lost time

Overall:

Low - Risk to be monitored to ensure it remains adequately controlled to an acceptable level.

Reference Documents

TFR Gold XQ1CCHC3pwss Cleaner -